

# Tronox Mine Sites R6/R9 Highways 509 and 605 Cibola and McKinley Counties, New Mexico Daily Report

**Date:** August 10, 2015

### Team:

Jeff Criner Yellow Jacket Drilling

## **Health and Safety:**

1. Weston team safety topics included physical hazards including slips, trips, falls, and dehydration.

# **Activities Completed:**

- 1. Yellow Jack Drilling finished completions at N-11 and N-16.
- 2. Site restoration was completed at N-10. Weston called (b) (6) to offer up a tour of the locations to ensure site restoration was satisfactory. (b) (6) indicated that he was out of town but would drive to the locations this coming weekend. Photodocumentation captured.
- 3. Hathorn transported the pump back to their shop for testing prior to reinstallation.

## Planned Activities for August 11, 2015:

- 1. Yellow Jacket Drilling to finish completions at N-15 and N-17.
- 2. EPA and Weston to meet with (b) (6) at 10 am to discuss and obtain access for locations N-6, N-8, N-9 and NKD-07. (b) (6) is in Colorado.
- 3. Discuss with (b) (6) one additional well on this property (N-19).
- 4. Hathorn to reinstall the (b) (6) pump.

### Schedule:

- 1. Current work rotation ends August 13, 2015. This could change to an earlier date (August 12) based on pending (b) (6) access to locations N-6, N-8, N-9 and NKD-07 and (b) (6) agreeing to one additional well.
- 2. Next work rotation is August 18 through September 3, 2015. Subject to change of course.

# Tronox Mine Sites R6/R9 Highways 509 and 605 Cibola and McKinley Counties, New Mexico Daily Report

# **Open Items:**

- 1. (b) (6) requested that we sample three of her other wells.
- 2. Schedule a call with Jet West Geophysical to review data obtained from the (b) (6) well. Tentative data for the conference call is August 14, 2015. Be on the lookout for a meeting invite.
- 3. Coordinate with Hathorn Well Service to reinstall the (b) (6) pump and check to ensure the system is operating correctly.
- 4. Check with ALS Laboratories and provide a status update regarding receipt of final data packages.
- 5. Prepare a tentative work schedule for the next rotation to allow for adequate landowner notification for drilling and sampling Rio wells MW-35-8, MW-35-9, and N-3.